

Photos highlighting some of the issues that will be addressed with the High School Repair Project



Floor in gymnasium had heaved and required repair - wood was cut and removed and replaced with cement. Floor is uneven in many areas.



Continual water damage on the floor of the gymnasium



Outdated and broken scoreboard.



Several roof leaks in the gymnasium ceiling.



Serious roof leak in weight room, tarp was installed to catch the water and then is directed to a hose which empties into a garbage can sump pump system.



Serious floor heaves and water damage in weight room.



Attempts have been made to repair floor but the cement is now heaving.



Wiring is open in ceiling waiting to be tied into the new wiring.



Roof leaks in Technology rooms over expensive electronic equipment.